TEMPEST excellence

SERVICE LETTER

Service Letter Number: SL-009

Subject: Air Filter TBO Replacement Time.

ALL FILTERS MUST BE REPLACED AT EACH AIR PUMP REPLACEMENT AND AT INTERVALS SPECIFIED BELOW

Vacuum System Air filters	Replacement Times
ARB3-5-1 Garter Filter	100 service hours or annually
AAD9-14-3 AAD9-14-5 AAD9-18-1	500 service hours or annually

Pressure System Air filters	Replacement Times
ARB3-5-1 AAD9-14-3 AAD9-14-5 AAD9-18-1	100 service hours or annually
AA2J4-4 AA2J4-6 AA2J4-7	500 service hours or annually

Replacement of Filter

To remove the filter, loosen or remove hose clamp at filter, remove hose from filter assembly. Remove assembly, replace filter element or filter assembly.
Inspect hoses for cracks, rubber separation, or slivers of rubber in the inside diameter of hose. Replace hose if cracks or separation is observed. Slivers can and do break off, if they get ingested in pump, premature failure can occur. Hose clamps or fittings should be replaced when broken, damaged or corroded.

CAUTION

Never apply compressed air to line or components installed on the aircraft. Excessive air pressure will damage the gyro instruments. Disconnect lines at both ends and blow from the instrument panel out

Any questions concerning this Service Letter should be directed to Aero Accessories, Inc.
Phone: 800-322-3200 // 336-449-5054 Fax: 336-449-5461
Website: www.aeroaccessories.com

ISSUED			REVISED				PAGE No.	REVISION
MO	DAY	YR	MO	DAY	YR	Aero Accessories, Inc. 1240 Springwood Avenue Gibsonville, N.C. USA	1 of 1	Original
06	25	09	00	00	00			