

Marvel-Schebler/Tillotson

Division Borg-Warner Corporation, 2195 South Elwin Road, Decatur, Illinois 62525

SERVICE BULLETIN

April 1979

#A2-79

TO: All registered manual holders

SUBJECT: Possible Carburetor Contamination

TIME OF COMPLIANCE: Carburetor to be exchanged before further flight.

CARBURETOR AFFECTED: Model HA, Part #A10-5243 used on Lycoming Engine Model O-540 L3C5D used in Cessna Aircraft TR182.

It is possible that contamination can occur in subject carburetor only, induced by casting impregnation process.

The following Serial Numbers list the Carburetors to be exchanged:

DF-1-100	DF-1-128	DF-1-162	DF-1-191	DF-1-231	DF-1-282
101	129	163	193	237	287
102	130	164	194	238	290
103	131	167	195	240	292
104	132	168	200	245	293
106	133	170	202	250	295
107	134	171	204	251	296
110	135	172	205	255	297
111	136	173	208	256	298
112	137	174	209	258	299
113	138	175	210	260	300
114	139	176	211	261	301
116	143	177	212	263	302
117	144	179	214	264	303
118	145	180	216	266	304
119	147	182	218	269	307
120	149	183	219	271	312
121	150	184	220	274	313
122	151	185	222	275	318
123	154	186	223	276	
124	157	187	225	277	
125	159	189	227	278	
127	161	190	229	279	

Request an exchange Carburetor from your Cessna distributor, it will be shipped to you from Lycoming. Return the original unit direct to Cessna.

The replacement unit Part A10-5243 will have a serial number 500 and up to show an airworthy unit has been supplied.



