

Marvel-Schebler/Tillotson

Division Borg-Warner Corporation, 2195 South Elwin Road, Decatur, Illinois 62525

SERVICE BULLETIN

NO. A1-76

May 26, 1976

SUBJECT: Carburetor Cleaning

MODELS: All

Our Aircraft Carburetor Overhaul procedures include a "recommended cleaning" process.

CAUTION

Follow the cleaner manufacturers instructions. DO NOT expose non metal parts to carburetor cleaning solutions.

Carburetor cleaning solutions are formulated to be used on metal only, and can have a very adverse effect on non metal materials.

Parts which are made with both metal and non metal — such as floats, gaskets, accelerator pump plungers etc. — must not be cleaned or rinsed with cleaners.

If non metal parts have been accidentally exposed to cleaners, they must be scrapped.

Non metal parts must not be steamed cleaned.

On the reverse side of this bulletin is a picture of the effects of non metal parts which have been exposed to carburetor cleaner.

Please advise your personnel.

MARVEL-SCHEBLER/TILLOTSON





EXAMPLES OF DAMAGED NON METAL
CARBURETOR PARTS WHICH HAVE BEEN
EXPOSED TO CARBURETOR CLEANER