

 <p><b>Continental Motors</b></p> <p>Telephone +1 800-326-0089</p>	<p><b>CSB05-8 Camshaft Gear Tool</b></p>	<p><b>Distributor Information Bulletin February 9, 2018</b></p> <p>DIB 2018-xx      Page 1 of 1</p>
---	--	---

To Our Valued Partners,

Critical Service Bulletin(CSB) 05-8 was revised July 18, 2017 requiring 100-hour inspections of the 631845, 655430, 655516, or 656031 camshaft gears or replacement thereof with 656818.

To aid our customers in compliance with CSB05-8, CMI partnered with a Stratus Tool Technologies and developed a kit containing the required tools to accomplish the modification. The tool kit includes pencil die grinder, carbide burr, and fixture assembly that meets the dimensional requirements to perform terminating action for CSB05-8C.

To order Fixture Assembly with Radial Grinder tool kit, contact Stratus Tool Technologies at [cmitool@stratustool.com](mailto:cmitool@stratustool.com) and reference part number ST05-8C. Standard cost for tool kit is \$599.15. Replacement carbide burrs can be purchased for \$24.99 using part number ST05-8CB.

For availability and purchasing, contact [cmitool@stratustool.com](mailto:cmitool@stratustool.com) with company name, contact name, and phone number. A Stratus Tool Technologies representative will contact you for purchasing details.

If you have any questions, please submit a request through your Customer Portal at <https://Synergy.tcmlink.com> or contact Customer Service at +1 800.326.0089 or +1 251.436.8292.